

Replacement Parts

List DF1500 HMA-2A

Direct Fire Spray Booth Insert Parts List

MASS Code

DF1500 HMA-2A

Direct Fire Spray Booth Insert Parts ONLY for:

Standard 1-1/2" valve train

Midco Insert # 1305001

AIR SWITCH COMPONENTS

Part #	Description	Qty
1346-61	Air Switch Low Pressure Tube-right Side	1
1346-62	Air Switch Low Pressure Tube-left Side	1
8483-14	1/8" NPT m x 1/4" tube str comp	2
8483-39	1/4" tube x 1/8" NPT f x 1/4" tube comp tee	1
8652-04	1/4" od x 032 wall AL-Tube	2.5 ft
8493-50	1/8" Coupling	1

PILOT COMPONENTS AND ACCESSORIES

Part #	Description	Qty
1342-03	Spark rod	1
1349-00	Electrode Boot	2
1360-03	Flame Rod	1
8483-53	5/16" tube x 1/4" tube comp Red Union	1
8484-44	#10 rng-tnge 35363	1
8484-79	Universal Bushing	1
8501-04	Flame Rod Wire	1
8501-05	Spark Rod Wire	1
8652-02	5/16" od x 032 wall AL-Tube	5 ft

BURNER AND VALVE TRAIN COMPONENTS - with gas switches to meet MASS Codes

Insert # 1305001

1-1/2" valve train

Part #	Description	Qty
1346-55	Burner Manifold Assembly	1
1346-60	Honeycomb Assembly	1
8402-70	0-15" W.C. Low Pressure Gauge	1
8402-71	0-10" W.C. Low Pressure Gauge	1
8404-65	1-1/2" Ball Valve w/o Side Tap	1
8425-62 or 8425-72 or 2118-07	Gas Switch Low	1
8425-73 or 8425-63 or 2118-06	Gas Switch High	1
8429-69	Siemens Controller	1
8419-34R	Belimo (35 second) Actuator Repair Kit	



Midco[®]
INTERNATIONAL

Midco[®] International Inc.
4140 West Victoria Street
Chicago, Illinois 60646
toll free 866.705.0514
tel 773.604.8700
fax 866.580.8700
web www.midcointernational.com
e-mail sales@midcointernational.com

AVOID ERROR IN PARTS SELECTION. When ordering use complete MIDCO Part Number and Description. Furnish Burner Model Number, Bill of Material Number and Serial Number (if available) from the specification plate found on the product.

IMPORTANT: Availability of parts as well as specifications are subject to change without notice. Please consult factory for item availability.



Quality Designed for Proven Performance

625
8472 98
Printed in USA